

2001 Workhorse Model P31042 Camera Truck

VIN: 5B4JP42R813332065

Condition: Excellent

Odometer: 27,100.00

Engine: 5. 7L V8

OFFERED WITH RESERVE

Transmission: Automatic with O.D.

Vehicle description as follows:

Grumman Olson 'Route Star' Aluminum walk-in van body

CCTV Inspection Truck

Strobe & work lights

15 gallon water storage tank with Shurflo water pump & retractable hose

Envirosight Rover 600 inspection camera:

- Extra sets of wheels**
- Spare parts**
- Rover 600 controllers (inside/out)**
- RA200 cable reel**

DC to AC power inverter

Colby DVD-R drive

Dual mounted desk monitors

Rear facing monitor

Back-up camera



Meticulously maintained by both district personnel and a local service station

LOT 302 - #22 - 2001 WORKHORSE GRUMMAN OLSON/STEPVAN MOD. P31042, ODOM: 27178;
VIN: 5B4JP42R813332065

